

Issue ID	Issue Category	Path No	Parish Name	Legal Status	Path Category	Description	Updates
51801	Obstructions	WN 1/1	Alford CP	Footpath	3	Access to the ROW south of the tunnel is blocked by large metal fence.	
51802	Missing	WN 1/1	Alford CP	Footpath	3	Stile destroyed. Metal gate blocking ROW. No ROW waymarkers in either direction.	
49134	Overgrowth	WN 1/1	Alford CP	Footpath	3	Stile is overgrown and impassable; gate is chained shut.	
		WN 1/2	Alford CP	Footpath	3		
43489		WN 1/3	Alford CP	Bridleway	3	Nuisance resolved	
53577	Improvement Request	WN 1/4	Alford CP	Bridleway	3	Gate unhinged/tied closed. Not operable on horseback on bend on busy road	
		WN 1/5	Alford CP	Footpath	3		
		WN 1/7	Alford CP	Footpath	3		
		WN 1/8	Alford CP	Footpath	3		
		WN 1/9	Alford CP	Footpath	3		
		WN 1/10	Alford CP	Footpath	3		